


VENTILATION AUDIT REPORT

SCHOOL:	Paxton Public School (2846)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Cessnock
LOCAL GOVERNMENT AREA:	Cessnock

2846 - Paxton Public School
Site Plan (11230)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Withdrawal Space - 1hb - (12.18 SQM)	● Student Space (5)	
B00A - R0002 - Canteen - (13.08 SQM)	Not Applicable	Circulation or storage space.
B00A - R0003 - Home Base - (46.99 SQM) - Teaching Space: 1	● Student Space (21)	
B00A - R0004 - Home Base - (47.12 SQM) - Teaching Space: 1	● Student Space (21)	
B00A - R0005 - Home Base - (46.96 SQM) - Teaching Space: 1	● Student Space (21)	
B00A - R0006 - Home Base - (47.04 SQM) - Teaching Space: 1	● Student Space (21)	
B00E - R0002 - Reading Area - (92.12 SQM)	● Student Space (42)	
OS 505 15436 - OS 505 15436 - Admin Staff/Principal/Secure Store - (76 SQM)	● Office (19)	