


VENTILATION AUDIT REPORT

SCHOOL:	Penrith Lakes Environmental Education Centre (5752)
AMU REGION:	Western Sydney
STATE ELECTORATE:	Penrith
LOCAL GOVERNMENT AREA:	Penrith

5752 - Penrith Lakes Environmental Education Centre
Site Plan (14778)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
BOA1 - R0001 - Special Programs Room - (35.21 SQM)	 Student Space (16)	
BOA1 - R0003 - Interview/Office - Type 3 - (13.63 SQM)	 Office (3)	
BOA1 - R0004 - Staff Kitchen - (10.09 SQM)	 Office (2)	
OS 503 12655 - OS 503 12655 - Admin Lib Staff/Principal/Clerk/Store - (152 SQM)	 Office (38)	