

VENTILATION AUDIT REPORT

SCHOOL:	Pilliga Public School (2870)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Narrabri

2870 - Pilliga Public School
Site Plan (12964)













1:442

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Home Base - (53.25 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0004 - Darkroom Space - (10.09 SQM)	 Office (2)	
B00A - R0009 - Home Base - (46.54 SQM) - Teaching Space: 1	 Student Space (21)	
B00A - R0010 - Home Base - (47.19 SQM) - Teaching Space: 1	 Student Space (21)	
B00A - R0011 - Principal - (8.69 SQM)	 Office (2)	
B00A - R0012 - Duplicating Workroom - (11.93 SQM)	 Office (2)	
B00B - R0002 - Staff Room - (19.17 SQM)	 Office (4)	
B00B - R0006 - Principal - (23.48 SQM)	 Office (5)	
B00B - R0007 - Staff Room Annexe - (32.68 SQM)	 Office (8)	
B00C - R0001 - Movement - (6.61 SQM)	Not Applicable	Circulation or storage space.
B00C - R0003 - Movement - (5.21 SQM)	Not Applicable	Circulation or storage space.
B00H - R0001 - Reading Area - (61.4 SQM)	 Student Space (28)	