

VENTILATION AUDIT REPORT

SCHOOL:	Pleasant Hills Public School (2886)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Wagga Wagga
LOCAL GOVERNMENT AREA:	Lockhart

2886 - Pleasant Hills Public School
Site Plan (12841)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Home Base - (53.6 SQM) - Teaching Space: 1	● Student Space (24)	
B00A - R0003 - Clerical Office - (14.75 SQM)	● Office (3)	
B00A - R0004 - Movement - (16.48 SQM)	Not Applicable	Circulation or storage space.
B00A - R0007 - Home Base - (33.18 SQM) - Teaching Space: 1	● Student Space (15)	
B00B - R0002 - Reading Area - (30.19 SQM)	● Student Space (14)	
B00B - R0005 - Staff Kitchen - (20.45 SQM)	● Office (5)	