

VENTILATION AUDIT REPORT

SCHOOL:	Premier Public School (2900)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Upper Hunter
LOCAL GOVERNMENT AREA:	Liverpool Plains

2900 - Premier Public School
Site Plan (10514)



1:899

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (49.13 SQM)	Not Applicable	Circulation or storage space.
B00A - R0003 - Home Base - (60.51 SQM)	● Student Space (28)	
B00A - R0004 - Withdrawal Space - 1hb - (9.26 SQM)	● Student Space (4)	
B00A - R0005 - Movement - (10.96 SQM)	Not Applicable	Circulation or storage space.
B00A - R0006 - Entry Vestibule - (17.44 SQM)	Not Applicable	Circulation or storage space.
B00A - R0007 - Principal - (11.82 SQM)	● Office (2)	
B00B - R0001 - Movement - (13.33 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Reading Area - (53.44 SQM)	● Student Space (24)	
B00B - R0003 - Staff Room - (22.09 SQM)	● Office (5)	
B00C - R0001 - Movement - (25.06 SQM)	Not Applicable	Circulation or storage space.
B00C - R0003 - Home Base - (61.28 SQM)	● Student Space (28)	
B00F - R0001 - Communal Space - (59.95 SQM)	● Student Space (27)	