


VENTILATION AUDIT REPORT

SCHOOL:	Quambone Public School (2919)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Coonamble

2919 - Quambone Public School
Site Plan (11830)











1:759

Printed: 30-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Principal - (14.32 SQM)	 Office (3)	
B00A - R0002 - Clerical Office - (14.39 SQM)	 Office (3)	
B00A - R0003 - Movement - (75.69 SQM)	Not Applicable	Circulation or storage space.
B00A - R0005 - Home Base - (56.83 SQM) - Teaching Space: 1	 Student Space (26)	
B00C - R0001 - Movement - (18.55 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Staff Room - (20.13 SQM)	 Office (5)	
B00C - R0003 - Staff Kitchen - (20.45 SQM)	 Office (5)	
B00E - R0001 - Movement - (12.8 SQM)	Not Applicable	Circulation or storage space.
B00E - R0002 - Reading Area - (46.59 SQM)	 Student Space (21)	
B00F - R0002 - Home Base - (57.6 SQM) - Teaching Space: 1	 Student Space (26)	
B00F - R0004 - Movement - (25.73 SQM)	Not Applicable	Circulation or storage space.
B00H - R0001 - Communal Space - (59.96 SQM)	 Student Space (27)	