

VENTILATION AUDIT REPORT

SCHOOL:	Raleigh Public School (2931)
AMU REGION:	North Coast
STATE ELECTORATE:	Oxley
LOCAL GOVERNMENT AREA:	Bellingen

2931 - Raleigh Public School
Site Plan (10719)













1:648

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Canteen - (5.23 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Practical Activities - 1hb - (18 SQM)	 Student Space (8)	
B00A - R0005 - Home Base - (52.78 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0008 - Movement - (61.74 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Movement - (17.42 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Movement - (30.17 SQM)	Not Applicable	Circulation or storage space.
B00D - R0002 - Clerical Office - (15.51 SQM)	 Office (3)	
B00D - R0003 - Clerical Office/Workroom - (22.31 SQM)	 Office (5)	
B00D - R0005 - Principal - (15.51 SQM)	 Office (3)	
B00D - R0006 - Staff Room - (20.54 SQM)	 Office (5)	
B00D - R0007 - Staff Room Annexe - (15.83 SQM)	 Office (3)	
B00D - R0008 - Sick Bay - (9.87 SQM)	 Student Space (4)	
B00D - R0011 - Staff Kitchen - (12.95 SQM)	 Office (3)	
OS 601 10538 - OS 601 10538 - Learning Unit - Standard/Withdrawal - (76 SQM)	 Student Space (35)	