


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Rand Public School (2933)</b>
<b>AMU REGION:</b>	<b>Southern NSW</b>
<b>STATE ELECTORATE:</b>	<b>Albury</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Federation</b>

2933 - Rand Public School  
Site Plan (13386)















1:1,097

Printed: 03-Sep-2021

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0007 - Special Programs Room - (21.61 SQM)	 Student Space (10)	
B00A - R0008 - Home Base - (61.17 SQM) - Teaching Space: 1	 Student Space (28)	
B00A - R0009 - Practical Activities - (23.09 SQM)	 Student Space (10)	
B00A - R0010 - Interview - (7.47 SQM)	 Office (1)	
B00B - R0001 - Staff Room - (8.09 SQM)	 Office (2)	
B00B - R0005 - Duplicating Workroom - (6.96 SQM)	 Office (1)	
B00B - R0006 - Movement - (8.07 SQM)	Not Applicable	Circulation or storage space.
B00B - R0007 - Clerical Office - (12.22 SQM)	 Office (3)	
B00B - R0008 - Staff Room - (14.2 SQM)	 Office (3)	
B00B - R0009 - Principal - (25.95 SQM)	 Office (6)	
B00C - R0002 - Home Base - (51.9 SQM) - Teaching Space: 1	 Student Space (24)	
B00C - R0003 - Reading Area - (52.26 SQM)	 Student Space (24)	
B00E - R0002 - Special Programs Room - (36.32 SQM)	 Student Space (16)	