


VENTILATION AUDIT REPORT

SCHOOL:	Rappville Public School (2937)
AMU REGION:	North Coast
STATE ELECTORATE:	Clarence
LOCAL GOVERNMENT AREA:	Richmond Valley

2937 - Rappville Public School
Site Plan (10723)











1:568

Printed: 18-Sep-2021

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0008 - Canteen - (12.66 SQM)	Not Applicable	Circulation or storage space.
B00A - R1001 - Home Base - (52.56 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R1003 - Principal - (12.64 SQM)	 Office (3)	
B00A - R1006 - Home Base - (52.56 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R1007 - Movement - (19.6 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Principal - (15.01 SQM)	 Office (3)	
B00C - R0004 - Staff Room - (9.12 SQM)	 Office (2)	
B00C - R0005 - Entry Vestibule - (9.92 SQM)	Not Applicable	Circulation or storage space.
B00C - R0007 - Sick Bay - (8.67 SQM)	 Student Space (4)	
B00C - R0008 - Clerical Office - (14.61 SQM)	 Office (3)	
B00C - R0009 - Reading Area - (64.2 SQM)	 Student Space (29)	