







VENTILATION AUDIT REPORT

SCHOOL:	Rockley Public School (2974)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Bathurst
LOCAL GOVERNMENT AREA:	Bathurst

Siteplan

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Withdrawal Space - 1hb - (10.65 SQM)	 Student Space (4)	
B00A - R0003 - Home Base - (53.5 SQM) - Teaching Space: 1	 Student Space (24)	
B00C - R0001 - Practical Activities - 1hb - (23.72 SQM)	 Student Space (11)	
B00F - R0001 - Home Base - (36.54 SQM) - Teaching Space: 1	 Student Space (16)	
B00H - R0002 - Home Base - (59.8 SQM) - Teaching Space: 1	 Student Space (27)	
OS 505 13883 - OS 505 13883 - Admin Staff/Principal/Secure Store - (76 SQM)	 Office (19)	