


VENTILATION AUDIT REPORT

SCHOOL:	Rocky River Public School (2983)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Northern Tablelands
LOCAL GOVERNMENT AREA:	Uralla

2983 - Rocky River Public School
Site Plan (10734)











1:1,038

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Duplicating Workroom - (9.5 SQM)	 Office (2)	
B00A - R0002 - Withdrawal Space - 2hb - (29.7 SQM)	 Student Space (13)	
B00A - R0003 - Home Base - (40.26 SQM) - Teaching Space: 1	 Student Space (18)	
B00A - R0004 - Home Base - (40.35 SQM) - Teaching Space: 1	 Student Space (18)	
B00A - R0005 - Movement - (7.88 SQM)	Not Applicable	Circulation or storage space.
B00A - R0006 - Principal - (13.25 SQM)	 Office (3)	
B00A - R0008 - Reading Area - (24.2 SQM)	 Student Space (11)	
B00A - R0009 - Practical Activities - 2hb - (31.6 SQM)	 Student Space (14)	
B00D - R0001 - Movement - (21.36 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Reading Area - (59.97 SQM)	 Student Space (27)	