

VENTILATION AUDIT REPORT









SCHOOL:	Rosebank Public School (2987)
AMU REGION:	North Coast
STATE ELECTORATE:	Lismore
LOCAL GOVERNMENT AREA:	Lismore

2987 - Rosebank Public School
Site Plan (11245)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Staff Room - (12.78 SQM)	 Office (3)	
B00A - R0004 - Principal - (11.81 SQM)	 Office (2)	
B00A - R0005 - Clerical Office - (9.66 SQM)	 Office (2)	
B00A - R0006 - Movement - (21.25 SQM)	Not Applicable	Circulation or storage space.
B00A - R0007 - Practical Activities - 1hb - (16.2 SQM)	 Student Space (7)	
B00A - R0008 - Home Base - (46.76 SQM) - Teaching Space: 1	 Student Space (21)	
B00A - R0009 - Home Base - (46.7 SQM) - Teaching Space: 1	 Student Space (21)	
B00A - R0010 - Practical Activities - 1hb - (16.17 SQM)	 Student Space (7)	
B00C - R0002 - Canteen - (22.81 SQM)	Not Applicable	Circulation or storage space.
B00G - R0002 - Reading Area - (92.82 SQM)	 Student Space (43)	