


VENTILATION AUDIT REPORT

SCHOOL:	Rosewood Public School (1996)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Albury
LOCAL GOVERNMENT AREA:	Snowy Valleys

2996 - Rosewood Public School
Site Plan (10696)












1:1,002

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Principal - (10.3 SQM)	 Office (2)	
B00A - R0002 - Home Base - (52.9 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0004 - Duplicating Workroom - (9.03 SQM)	 Office (2)	
B00A - R0005 - Movement - (10.5 SQM)	Not Applicable	Circulation or storage space.
B00D - R0002 - Movement - (25.13 SQM)	Not Applicable	Circulation or storage space.
B00D - R0004 - Reading Area - (47.87 SQM)	 Student Space (22)	
B00D - R0005 - Home Base - (47.87 SQM) - Teaching Space: 1	 Student Space (22)	
B00D - R0006 - Entry Vestibule - (10.63 SQM)	Not Applicable	Circulation or storage space.
B00D - R0007 - Clerical Office - (11.42 SQM)	 Office (2)	
B00D - R0008 - Staff Room - (9.53 SQM)	 Office (2)	
B00D - R0009 - Sick Bay - (5.64 SQM)	 Student Space (2)	
B00D - R0010 - Principal - (10.83 SQM)	 Office (2)	