

VENTILATION AUDIT REPORT

SCHOOL:	Rowena Public School (3580)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Walgett

3580 - Rowena Public School
Site Plan (10698)













1:699

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0004 - Reading Area - (58.22 SQM)	 Student Space (27)	
B00A - R0006 - Staff Room - (17.52 SQM)	 Office (4)	
B00A - R0007 - Principal - (16.57 SQM)	 Office (4)	
B00A - R0008 - Sick Bay - (6.25 SQM)	 Student Space (2)	
B00A - R0010 - Entry Vestibule - (19.39 SQM)	Not Applicable	Circulation or storage space.
B00A - R0012 - Clerical Office - (17.08 SQM)	 Office (4)	
B00B - R0002 - Practical Activities - 1hb - (18.19 SQM)	 Student Space (8)	
B00B - R0003 - Home Base - (58.64 SQM) - Teaching Space: 1	 Student Space (27)	
B00B - R0009 - Home Base - (58.63 SQM) - Teaching Space: 1	 Student Space (27)	
B00B - R0010 - Practical Activities - 1hb - (18.18 SQM)	 Student Space (8)	
B00B - R0011 - Special Programs Room - (40.62 SQM)	 Student Space (18)	