


VENTILATION AUDIT REPORT

SCHOOL:	Royal North Shore Hospital School (5544)
AMU REGION:	Northern Sydney
STATE ELECTORATE:	Lane Cove
LOCAL GOVERNMENT AREA:	Willoughby

5544 - Royal North Shore Hospital School
Site Plan (12959)



1:2,482

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00B - R0001 - Home Base - (20.17 SQM) - Teaching Space: 1	 Student Space (9)	
B00B - R0002 - Clerical Office - (11.09 SQM)	 Office (2)	