


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Royal Prince Alfred Hospital School (5543)</b>
<b>AMU REGION:</b>	<b>Sydney</b>
<b>STATE ELECTORATE:</b>	<b>Newtown</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Sydney</b>

5543 - Royal Prince Alfred Hospital School  
Site Plan (12960)




1:1,030

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Staff Room Annexe - (10.69 SQM)	 Office (2)	
B00A - R0002 - Clerical Office/Workroom - (10.69 SQM)	 Office (2)	