


VENTILATION AUDIT REPORT

| | |
|-------------------------------|-----------------------------------|
| SCHOOL: | Rugby Public School (3012) |
| AMU REGION: | Southern NSW |
| STATE ELECTORATE: | Goulburn |
| LOCAL GOVERNMENT AREA: | Hilltops |

3012 - Rugby Public School
Site Plan (11920)








1:521

Printed: 21-Mar-2020

Ventilation Audit Key

| Category | Description |
|---|--|
|  | Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings. |
|  | Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces. |

| Entity Location | Audit Condition Classification (Capacity) | Comment |
|--|--|-------------------------------|
| B00A - R0002 - Clerical Office - (27.31 SQM) |  Office (6) | |
| B00A - R0003 - Movement - (31.61 SQM) | Not Applicable | Circulation or storage space. |
| B00A - R0005 - Clerical Office - (7.92 SQM) |  Office (1) | |
| B00B - R0003 - Home Base - (55.2 SQM) |  Student Space (25) | |
| B00B - R0004 - Principal - (6.74 SQM) |  Office (1) | |
| B00B - R0006 - Special Programs Room - (26.79 SQM) |  Student Space (12) | |