


VENTILATION AUDIT REPORT

SCHOOL:	Rumbalara Environmental Education Centre (5740)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Gosford
LOCAL GOVERNMENT AREA:	Central Coast

5740 - Rumbalara Environmental Education Centre
Site Plan (13491)






1:254

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Outdoor Learning Area - (101.95 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Movement - (80.04 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Clerical Office - (14.11 SQM)	 Office (3)	
B00A - R0006 - Principal - (25.21 SQM)	 Office (6)	
B00B - R0001 - Tiered Learning Space - (42.49 SQM)	 Student Space (19)	
B00B - R0007 - Outdoor Learning Area - (40.76 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Movement - (77.82 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Movement - (59.75 SQM)	Not Applicable	Circulation or storage space.
B00C - R0003 - Canteen - (13.92 SQM)	Not Applicable	Circulation or storage space.
B00C - R0004 - Canteen - (6.91 SQM)	Not Applicable	Circulation or storage space.