


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Rye Park Public School (3024)</b>
<b>AMU REGION:</b>	<b>Southern NSW</b>
<b>STATE ELECTORATE:</b>	<b>Goulburn</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Hilltops</b>

3024 - Rye Park Public School  
Site Plan (11255)












1:625

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Staff Room - (9 SQM)	 Office (2)	
B00A - R0002 - Clerical Office - (11.04 SQM)	 Office (2)	
B00A - R0003 - Principal - (10.6 SQM)	 Office (2)	
B00A - R0004 - Home Base - (52.93 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0005 - Home Base - (52.79 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0009 - Special Programs Room - (22.44 SQM)	 Student Space (10)	
B00B - R0002 - Reading Area - (27.41 SQM)	 Student Space (12)	
B00E - R0002 - Clerical Office/Workroom - (16.25 SQM)	 Office (4)	
B00E - R0003 - Interview - (16.2 SQM)	 Office (4)	
B00E - R0006 - Movement - (6.87 SQM)	Not Applicable	Circulation or storage space.