
VENTILATION AUDIT REPORT



SCHOOL:	School of the Air (5302)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Broken Hill

5302 - School of the Air Site Plan (12399)



Ventilation Audit Report

9/10/2021

Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
\bigcirc	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Staff Room - (46.06 SQM)	Office (11)	
B00A - R0015 - Public Entry - (33.36 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Practical Activities - 1hb - (21.63 SQM)	Student Space (10)	
B00C - R0004 - Home Base - (64.05 SQM) - Teaching Space: 1	Student Space (29)	
B00C - R0005 - Withdrawal Space - 2hb - (10.85 SQM)	Student Space (5)	
B00C - R0006 - Home Base - (64.05 SQM) - Teaching Space: 1	Student Space (29)	
B00C - R0008 - Practical Activities - 1hb - (21.63 SQM)	Student Space (10)	
B00D - R0001 - Entry Vestibule - (8.31 SQM)	Not Applicable	Circulation or storage space.
B00D - R0002 - Clerical/Printing - (8.12 SQM)	Not Applicable	Circulation or storage space.
B00D - R0003 - Practical Activities - Pre - (49.62 SQM)	Student Space (23)	
OS 508 15342 - OS 508 15342 - Administration - (114 SQM)	Office (28)	
OS 601 13886 - OS 601 13886 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	
OS 601 13887 - OS 601 13887 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	
OS 601 13888 - OS 601 13888 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	