


VENTILATION AUDIT REPORT

SCHOOL:	Somerton Public School (3079)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Tamworth

3079 - Somerton Public School
Site Plan (13326)













1:399

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00B - R0004 - Staff Room - (24.98 SQM)	 Office (6)	
B00B - R0008 - Withdrawal Space - 1hb - (5.96 SQM)	 Student Space (2)	
B00B - R0009 - Home Base - (51.74 SQM) - Teaching Space: 1	 Student Space (24)	
B00B - R0010 - Reading Area - (36.26 SQM)	 Student Space (16)	
B00B - R0012 - Practical Activities - 1hb - (15.72 SQM)	 Student Space (7)	
B00B - R0013 - Movement - (30.96 SQM)	Not Applicable	Circulation or storage space.
B00B - R0015 - Principal - (14.28 SQM)	 Office (3)	
B00B - R0016 - Clerical Office - (14.98 SQM)	 Office (3)	
B00B - R0017 - Reading Area - (34.46 SQM)	 Student Space (15)	
B00B - R0018 - Movement - (13.97 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Communal Space - (59.86 SQM)	 Student Space (27)	
OS 602 14075 - OS 602 14075 - Learning Unit - Standard With P.A.A. - (76 SQM)	 Student Space (35)	