








VENTILATION AUDIT REPORT

SCHOOL:	South Western Sydney Region Suspension Centre (741)
AMU REGION:	South Western Sydney
STATE ELECTORATE:	
LOCAL GOVERNMENT AREA:	

Siteplan

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Independent Learning Space - (46.56 SQM)	 Student Space (21)	
B00A - R0003 - Staff Kitchen - (15.55 SQM)	 Office (3)	
B00A - R0007 - Movement - (5 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Staff Study - (11.13 SQM)	 Office (2)	
B00A - R0010 - Staff Study - (10.64 SQM)	 Office (2)	
B00A - R0011 - Movement - (10.04 SQM)	Not Applicable	Circulation or storage space.
B00A - R0014 - Movement - (13.95 SQM)	Not Applicable	Circulation or storage space.
B00A - R0015 - Independent Learning Space - (22.9 SQM)	 Student Space (10)	
B00A - R0016 - Movement - (16.29 SQM)	Not Applicable	Circulation or storage space.
B00A - R0017 - Seminar Space - (10.52 SQM)	 Office (2)	
B00A - R0018 - Staff Study - (13.4 SQM)	 Office (3)	
B00A - R0019 - Movement - (13.32 SQM)	Not Applicable	Circulation or storage space.