


VENTILATION AUDIT REPORT

SCHOOL:	Spring Hill Public School (3089)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Orange
LOCAL GOVERNMENT AREA:	Orange

3089 - Spring Hill Public School
Site Plan (12010)










1:801

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (12 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Practical Activities - 2hb - (47.32 SQM)	 Student Space (21)	
B00A - R0003 - Home Base - (47.23 SQM) - Teaching Space: 1	 Student Space (21)	
B00A - R0004 - Home Base - (54.49 SQM) - Teaching Space: 1	 Student Space (25)	
B00A - R0007 - Principal - (10.38 SQM)	 Office (2)	
B00A - R0008 - Entry Vestibule - (10.36 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Reading Area - (59.81 SQM)	 Student Space (27)	
OS 505 13089 - OS 505 13089 - Admin Staff/Principal/Secure Store - (76 SQM)	 Office (19)	
OS 531 14150 - OS 531 14150 - Library - (76 SQM)	 Student Space (35)	