## **VENTILATION AUDIT REPORT**



SCHOOL:	Spring Ridge Public School (3091)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Upper Hunter
LOCAL GOVERNMENT AREA:	Liverpool Plains

3091 - Spring Ridge Public School Site Plan (12011)



## Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
$\bigcirc$	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (77.64 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Reading Area - (75.59 SQM)	Student Space (35)	
B00B - R0001 - Movement - (46.35 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Home Base - (51.78 SQM) - Teaching Space: 1	Student Space (24)	
B00B - R0006 - Home Base - (58.76 SQM) - Teaching Space: 1	Student Space (27)	
B00B - R0007 - Practical Activities - 1hb - (6.7 SQM)	Student Space (3)	
B00B - R0009 - Withdrawal Space - 1hb - (10.9 SQM)	Student Space (5)	
B00B - R0010 - Interview - (7.22 SQM)	Office (1)	
B00B - R0011 - Withdrawal Space - 2hb - (22.19 SQM)	Student Space (10)	
B00E - R0002 - Clerical Office - (36.79 SQM)	Office (9)	
B00E - R0004 - Entry Vestibule - (7.43 SQM)	Not Applicable	Circulation or storage space.
B00E - R0005 - Principal - (9.02 SQM)	Office (2)	
B00G - R0001 - Home Base - (63.72 SQM) - Teaching Space: 1	Student Space (29)	
B00H - R0001 - Home Base - (59.95 SQM) - Teaching Space: 1	Student Space (27)	