


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Spring Terrace Public School (3093)</b>
<b>AMU REGION:</b>	<b>North Western NSW</b>
<b>STATE ELECTORATE:</b>	<b>Orange</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Cabonne</b>

3093 - Spring Terrace Public School  
Site Plan (13458)









1:1,532

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (57.62 SQM) - Teaching Space: 1	 Student Space (26)	
B00A - R0003 - Clerical Office - (15.52 SQM)	 Office (3)	
B00A - R0004 - Reading Area - (12.93 SQM)	 Student Space (5)	
B00F - R0001 - Communal Space - (59.74 SQM)	 Student Space (27)	
OS 500 18119 - OS 500 18119 - Admin - Library - (133 SQM)	 Office (33)	
OS 601 13781 - OS 601 13781 - Learning Unit - Standard/Withdrawal - (76 SQM)	 Student Space (35)	