


VENTILATION AUDIT REPORT

SCHOOL:	St George Hospital School (5513)
AMU REGION:	Sydney
STATE ELECTORATE:	Kogarah
LOCAL GOVERNMENT AREA:	Georges River

5513 - St George Hospital School
Site Plan (13353)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R1002 - Clerical Office - (10.93 SQM)	 Office (2)	
B00A - R1003 - Home Base - (27.36 SQM) - Teaching Space: 1	 Student Space (12)	