


VENTILATION AUDIT REPORT











SCHOOL:	Stanford Merthyr Infants School (5133)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Cessnock
LOCAL GOVERNMENT AREA:	Cessnock

5133 - Stanford Merthyr Infants School
Site Plan (11314)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Practical Activities - 1hb - (44.01 SQM)	 Student Space (20)	
B00A - R0002 - Canteen - (7.68 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Home Base - (46.65 SQM) - Teaching Space: 1	 Student Space (21)	
B00A - R0005 - Home Base - (46.61 SQM) - Teaching Space: 1	 Student Space (21)	
B00C - R0002 - Practical Activities - 1hb - (19.86 SQM)	 Student Space (9)	
B00C - R0004 - Home Base - (58.16 SQM) - Teaching Space: 1	 Student Space (26)	
B00C - R0005 - Withdrawal Space - 2hb - (10.68 SQM)	 Student Space (4)	
B00C - R0006 - Home Base - (58.16 SQM) - Teaching Space: 1	 Student Space (26)	
B00C - R0008 - Practical Activities - 1hb - (19.86 SQM)	 Student Space (9)	
B00E - R0001 - Communal Space - (111.46 SQM)	 Student Space (51)	
B00E - R0002 - Raised Platform - (15.77 SQM)	Not Applicable	Circulation or storage space.
OS 503 11124 - OS 503 11124 - Admin Lib Staff/Principal/Clerk/Store - (152 SQM)	 Office (38)	