

VENTILATION AUDIT REPORT

SCHOOL:	Stratford Public School (3119)
AMU REGION:	North Coast
STATE ELECTORATE:	Upper Hunter
LOCAL GOVERNMENT AREA:	Mid-Coast

3119 - Stratford Public School
Site Plan (11937)











1:831

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office - (8.98 SQM)	 Office (2)	
B00A - R0002 - Principal - (12.36 SQM)	 Office (3)	
B00A - R0003 - Staff Room - (10.77 SQM)	 Office (2)	
B00A - R0006 - Movement - (25.99 SQM)	Not Applicable	Circulation or storage space.
B00A - R0007 - Special Programs Room - (46.8 SQM)	 Student Space (21)	
B00A - R0008 - Home Base - (52.81 SQM) - Teaching Space: 1	 Student Space (24)	
B00B - R0005 - Movement - (11.64 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Home Base - (53.8 SQM) - Teaching Space: 1	 Student Space (24)	
B00E - R0003 - Practical Activities - 1hb - (5.47 SQM)	 Student Space (2)	
B00G - R0001 - Reading Area - (59.93 SQM)	 Student Space (27)	