

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Stratheden Public School (3122)</b>
<b>AMU REGION:</b>	<b>North Coast</b>
<b>STATE ELECTORATE:</b>	<b>Clarence</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Richmond Valley</b>

3122 - Stratheden Public School  
Site Plan (10624)







1:723

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Staff Kitchen - (12.56 SQM)	 Office (3)	
B00A - R0009 - Home Base - (66.96 SQM) - Teaching Space: 1	 Student Space (31)	
B00A - R0010 - Movement - (17.32 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Movement - (20.86 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	 Student Space (27)	
OS 500 18110 - OS 500 18110 - Admin - Library - (133 SQM)	 Office (33)	