


VENTILATION AUDIT REPORT

SCHOOL:	Stuart Town Public School (3127)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Dubbo
LOCAL GOVERNMENT AREA:	Dubbo

3127 - Stuart Town Public School
Site Plan (13161)










1:629

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Duplicating Workroom - (19.46 SQM)	 Office (4)	
B00A - R0002 - Home Base - (45.24 SQM) - Teaching Space: 1	 Student Space (20)	
B00A - R0004 - Home Base - (49.23 SQM) - Teaching Space: 1	 Student Space (22)	
B00A - R0005 - Clerical Office - (10.84 SQM)	 Office (2)	
B00A - R0006 - Principal - (11.41 SQM)	 Office (2)	
B00A - R0007 - Staff Room - (7.94 SQM)	 Office (1)	
B00B - R0001 - Reading Area - (28.95 SQM)	 Student Space (13)	