


VENTILATION AUDIT REPORT

SCHOOL:	Talbingo Public School (4374)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Wagga Wagga
LOCAL GOVERNMENT AREA:	Snowy Valleys

4374 - Talbingo Public School
Site Plan (11326)










1:1,043

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Practical Activities - 1hb - (21.96 SQM)	 Student Space (10)	
B00A - R0004 - Entry Vestibule - (109.01 SQM)	Not Applicable	Circulation or storage space.
B00A - R0005 - Staff Room - (19.87 SQM)	 Office (4)	
B00A - R0006 - Canteen - (10.01 SQM)	Not Applicable	Circulation or storage space.
B00A - R0017 - Home Base - (56.76 SQM) - Teaching Space: 1	 Student Space (26)	
B00A - R0018 - Home Base - (56.68 SQM) - Teaching Space: 1	 Student Space (26)	
B00A - R0024 - Clerical Office - (12.89 SQM)	 Office (3)	
B00A - R0025 - Principal - (12.96 SQM)	 Office (3)	
B00A - R0027 - Reading Area - (71.51 SQM)	 Student Space (33)	