

VENTILATION AUDIT REPORT

| | |
|-------------------------------|--------------------------------------|
| SCHOOL: | Tallimba Public School (3153) |
| AMU REGION: | Southern NSW |
| STATE ELECTORATE: | Cootamundra |
| LOCAL GOVERNMENT AREA: | Bland |

3153 - Tallimba Public School
Site Plan (11811)










1:1,096

Printed: 21-Mar-2020

Ventilation Audit Key

| Category | Description |
|---|--|
|  | Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings. |
|  | Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces. |

| Entity Location | Audit Condition Classification (Capacity) | Comment |
|--|--|-------------------------------|
| B00A - R0001 - Clerical Office - (14.93 SQM) |  Office (3) | |
| B00A - R0002 - Home Base - (56.73 SQM) - Teaching Space: 1 |  Student Space (26) | |
| B00A - R0005 - Movement - (23.73 SQM) | Not Applicable | Circulation or storage space. |
| B00A - R0006 - Entry Vestibule - (6.03 SQM) | Not Applicable | Circulation or storage space. |
| B00A - R0008 - Computer Room - (46.46 SQM) |  Student Space (21) | |
| B00B - R0002 - Home Base - (51.2 SQM) - Teaching Space: 1 |  Student Space (23) | |
| B00B - R0004 - Staff Room - (13.23 SQM) |  Office (3) | |
| B00B - R0005 - Movement - (13.09 SQM) | Not Applicable | Circulation or storage space. |
| B00C - R0001 - Movement - (22.11 SQM) | Not Applicable | Circulation or storage space. |
| B00C - R0002 - Reading Area - (48.58 SQM) |  Student Space (22) | |
| B00G - R0001 - Reading Area - (59.86 SQM) |  Student Space (27) | |