VENTILATION AUDIT REPORT



SCHOOL:	Tallong Public School (3154)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Goulburn
LOCAL GOVERNMENT AREA:	Goulburn Mulwaree





Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces. The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Practical Activities - 1hb - (5.71 SQM)	Student Space (2)	
B00A - R0004 - Withdrawal Space - 1hb - (37.4 SQM)	Student Space (17)	
B00A - R0005 - Principal - (7.43 SQM)	Office (1)	
B00B - R0007 - Movement - (18.23 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Reading Area - (28.31 SQM)	Student Space (13)	
B00C - R0005 - Clerical Office - (8.34 SQM)	Office (2)	
B00F - R0002 - Reading Area - (37.69 SQM)	Student Space (17)	
B00H - R0001 - Staff Room - (29.28 SQM)	Office (7)	
B00H - R0002 - Staff Kitchen - (10.49 SQM)	Office (2)	
B00H - R0005 - Staff Room - (14.5 SQM)	Office (3)	
B00H - R0006 - Staff Room - (10.62 SQM)	Office (2)	
B00H - R0007 - Staff Room - (10.65 SQM)	Office (2)	
B00H - R0008 - Staff Room - (14.24 SQM)	Office (3)	
B00J - R0001 - Home Base - (58.3 SQM) - Teaching Space: 1	Student Space (27)	
B00J - R0003 - Practical Activities - (6.23 SQM)	Student Space (2)	
NS 100 13822 - NS 100 13822 - Learning Unit - Single Primary/PAA - (76 SQM)	Student Space (35)	
OS 601 13337 - OS 601 13337 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	