


VENTILATION AUDIT REPORT

SCHOOL:	Tambar Springs Public School (3156)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Gunnedah

3156 - Tambar Springs Public School
Site Plan (13113)










1:966

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B001 - R0001 - Principal - (10.78 SQM)	 Office (2)	
B001 - R0002 - Clerical Office - (11.09 SQM)	 Office (2)	
B001 - R0004 - Home Base - (66.88 SQM) - Teaching Space: 1	 Student Space (31)	
B001 - R0005 - Entry Vestibule - (8.31 SQM)	Not Applicable	Circulation or storage space.
B002 - R0001 - Home Base - (40.08 SQM) - Teaching Space: 1	 Student Space (18)	
B002 - R0003 - Reading Area - (42.5 SQM)	 Student Space (19)	
B002 - R0004 - Canteen - (10.3 SQM)	Not Applicable	Circulation or storage space.
B002 - R0005 - Movement - (11.4 SQM)	Not Applicable	Circulation or storage space.
B002 - R0006 - Staff Room - (9.61 SQM)	 Office (2)	
B005 - R0001 - Communal Space - (59.95 SQM)	 Student Space (27)	