
## **VENTILATION AUDIT REPORT**



SCHOOL:	Tangara School (5684)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Wollondilly
LOCAL GOVERNMENT AREA:	Wingecarribee



Ventilation Audit Report

9/10/2021

1/3

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
$\bigcirc$	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0004 - Home Base - M - (55.1 SQM) - Teaching Space: 1	Student Space (25)	
B00A - R0005 - Home Base - M - (54.32 SQM) - Teaching Space: 1	Student Space (25)	
B00A - R0008 - Practical Activities - M - 1hb - (55.09 SQM)	Student Space (25)	
B00A - R0016 - Principal - (14.73 SQM)	Office (3)	
B00A - R0022 - Entry Vestibule - (8.73 SQM)	Not Applicable	Circulation or storage space.
B00A - R0027 - Principal - (15.46 SQM)	Office (3)	
B00A - R0029 - Clerical Office/Workroom - (40.36 SQM)	Office (10)	
B00A - R0030 - Movement - (74.35 SQM)	Not Applicable	Circulation or storage space.
B00B - R0009 - Movement - (45.8 SQM)	Not Applicable	Circulation or storage space.
B00B - R0010 - Movement - (12.9 SQM)	Not Applicable	Circulation or storage space.
B00B - R0012 - Home Base - (48.14 SQM) - Teaching Space: 1	Student Space (22)	
B00B - R0015 - Home Base - (52.46 SQM) - Teaching Space: 1	Student Space (24)	
B00C - R0001 - Hydrotherapy - Pool - (51.06 SQM)	Not Applicable	Circulation or storage space.
OS 523 18325 - OS 523 18325 - Staff Study With Toilets - (76 SQM)	Office (19)	
OS 603 12920 - OS 603 12920 - Learning Unit - Standard With P.A.A. A/C - (76 SQM)	Student Space (35)	