


VENTILATION AUDIT REPORT

SCHOOL:	Tanja Public School (3159)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Bega
LOCAL GOVERNMENT AREA:	Bega Valley

3159 - Tanja Public School
Site Plan (11488)



1:555

Printed: 31-Oct-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (10.61 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Reading Area - (29.7 SQM)	● Student Space (13)	
B00C - R0001 - Movement - (13.09 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Practical Activities - 1hb - (29.24 SQM)	● Student Space (13)	
B00C - R0003 - Staff Kitchen - (12.92 SQM)	● Office (3)	
B00C - R0007 - Movement - (7.97 SQM)	Not Applicable	Circulation or storage space.
B00C - R0008 - Principal - (8.94 SQM)	● Office (2)	
B00C - R0010 - Duplicating Workroom - (5.62 SQM)	● Office (1)	
B00C - R0011 - Withdrawal Space - 1hb - (14.12 SQM)	● Student Space (6)	
B00C - R0012 - Clerical Office - (11.91 SQM)	● Office (2)	
B00E - R0003 - Reading Area - (61.17 SQM) - Teaching Space: 1	● Student Space (28)	
OS 601 13734 - OS 601 13734 - Learning Unit - Standard/Withdrawal - (76 SQM)	● Student Space (35)	