
## **VENTILATION AUDIT REPORT**



SCHOOL:	Thalgarrah Environmental Education Centre (5680)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Northern Tablelands
LOCAL GOVERNMENT AREA:	Armidale

5680 - Thalgarrah Environmental Education Centre Site Plan (11498)



## **Ventilation Audit Key**

Category	Description
	Category A  Operate this space in line with <a href="COVID safe school operations">COVID safe school operations</a> . It has the required level of natural ventilation.  NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B  This space should be occupied at 1 person per 4m <sup>2</sup> to comply with COVID safe school operations and the guided use of spaces.  The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0007 - Clerical Office - (18.55 SQM)	Office (4)	
B00A - R0008 - Staff Room - (12.87 SQM)	Office (3)	
B00A - R0009 - Principal - (13.32 SQM)	Office (3)	
B00A - R0011 - Sick Bay - (5.89 SQM)	Student Space (2)	
B00A - R0012 - Movement - (5.89 SQM)	Not Applicable	Circulation or storage space.
B00A - R0013 - General Learning Space - (58.37 SQM) - Teaching Space: 1	Student Space (27)	
B00A - R0014 - General Learning Space - (53.97 SQM) - Teaching Space: 1	Student Space (25)	
B00A - R0015 - Darkroom Space - (10.87 SQM)	Office (2)	
B00A - R0016 - Duplicating Workroom - (11.11 SQM)	Office (2)	
B00A - R0018 - Movement - (11.03 SQM)	Not Applicable	Circulation or storage space.
B00C - R0004 - Dormitory - (35.6 SQM)	Office (8)	
B00C - R0006 - Dormitory - (44.73 SQM)	Office (11)	
B00H - R0001 - Special Programs Room - (20.36 SQM)	Student Space (9)	
B00J - R0001 - Craft Room - (20.66 SQM)	Office (5)	
B00K - R0001 - General Assistants - (52.44 SQM)	Office (13)	