
VENTILATION AUDIT REPORT



SCHOOL:	Tharbogang Public School (3195)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Murray
LOCAL GOVERNMENT AREA:	Griffith



Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (18.48 SQM)	Not Applicable	Circulation or storage space.
B00A - R0005 - Home Base - (50.48 SQM) - Teaching Space: 1	Student Space (23)	
B00B - R0001 - Movement - (16.51 SQM)	Not Applicable	Circulation or storage space.
B00B - R0007 - Home Base - (51.2 SQM) - Teaching Space: 1	Student Space (23)	
B00C - R0001 - Practical Activities - 1hb - (33.62 SQM)	Student Space (15)	
B00C - R0005 - Movement - (22 SQM)	Not Applicable	Circulation or storage space.
B00C - R0006 - Home Base - (60.43 SQM) - Teaching Space: 1	Student Space (28)	
B00D - R0002 - Movement - (17.21 SQM)	Not Applicable	Circulation or storage space.
B00G - R0001 - Reading Area - (59.86 SQM)	Student Space (27)	
OS 500 18122 - OS 500 18122 - Admin - Library - (133 SQM)	Office (33)	