


VENTILATION AUDIT REPORT













SCHOOL:	The Childrens Hospital School (5751)
AMU REGION:	Western Sydney
STATE ELECTORATE:	Seven Hills
LOCAL GOVERNMENT AREA:	Parramatta

5751 - The Childrens Hospital School
Site Plan (14550)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (38.43 SQM) - Teaching Space: 1	 Student Space (17)	
B00A - R0002 - Practical Activities - 1hb - (8.83 SQM)	 Student Space (4)	
B00A - R0004 - Home Base - (63.82 SQM) - Teaching Space: 1	 Student Space (29)	
B00A - R0005 - Practical Activities - 1hb - (6.14 SQM)	 Student Space (2)	
B00A - R1001 - Home Base - (48.09 SQM) - Teaching Space: 1	 Student Space (22)	
B00A - R1002 - Practical Activities - 1hb - (5.78 SQM)	 Student Space (2)	
B00A - R1003 - Practical Activities - 1hb - (11.44 SQM)	 Student Space (5)	
B00A - R1004 - Communal Space - (49.96 SQM)	 Student Space (23)	
B00A - R1007 - Principal - (12.98 SQM)	 Office (3)	
B00A - R1010 - Staff Room - (30.26 SQM)	 Office (7)	
B00A - R1011 - Staff Room Annexe - (6.2 SQM)	 Office (1)	
B00A - R1013 - Clerical Office/Workroom - (30.55 SQM)	 Office (7)	