


VENTILATION AUDIT REPORT

SCHOOL:	Tibooburra Outback Public School (3211)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Unincorporated

3211 - Tibooburra Outback Public School
Site Plan (12876)



1:840

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (38.99 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Home Base - (53.2 SQM) - Teaching Space: 1	● Student Space (24)	
B00A - R0003 - Home Base - (52.91 SQM) - Teaching Space: 1	● Student Space (24)	
B00A - R0005 - Withdrawal Space - 1hb - (12.36 SQM)	● Student Space (5)	
B00A - R0006 - Movement - (18.46 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Communal Space - (166.21 SQM)	● Student Space (77)	
B00E - R0001 - Movement - (51.5 SQM)	Not Applicable	Circulation or storage space.
B00H - R0001 - Reading Area - (60 SQM)	● Student Space (27)	
B00H - R0002 - Movement - (6.19 SQM)	Not Applicable	Circulation or storage space.
OS 601 13895 - OS 601 13895 - Learning Unit - Standard/Withdrawal - (76 SQM)	● Student Space (35)	
OS 751 15124 - OS 751 15124 - Learning Unit - ESL - (76 SQM)	● Student Space (35)	