
VENTILATION AUDIT REPORT



SCHOOL:	Tirranna Public School (3222)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Goulburn
LOCAL GOVERNMENT AREA:	Goulburn Mulwaree



Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
\bigcirc	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office/Workroom - (12.81 SQM)	Office (3)	
B00A - R0002 - Reading Area - (45.82 SQM)	Student Space (21)	
B00A - R0003 - Entry Vestibule - (24.2 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Home Base - (44.35 SQM) - Teaching Space: 1	Student Space (20)	
B00A - R0007 - Movement - (10.09 SQM)	Not Applicable	Circulation or storage space.
B00A - R0012 - Raised Platform - (29.13 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Home Base - (61.18 SQM) - Teaching Space: 1	Student Space (28)	