


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Trunkey Public School (3260)</b>
<b>AMU REGION:</b>	<b>North Western NSW</b>
<b>STATE ELECTORATE:</b>	<b>Bathurst</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Bathurst</b>







3260 - Trunkey Public School  
Site Plan (11525)



Printed: 01-May-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Clerical Office - (32.71 SQM)	 Office (8)	
B00A - R0004 - Practical Activities - (24.97 SQM)	 Student Space (11)	
B00B - R0002 - Withdrawal Space - 1hb - (41.21 SQM)	 Student Space (19)	
B00B - R0004 - Reading Area - (8.87 SQM)	 Student Space (4)	
B00E - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	
OS 601 13896 - OS 601 13896 - Learning Unit - Standard/Withdrawal - (76 SQM)	 Student Space (35)	