## **VENTILATION AUDIT REPORT**



SCHOOL:	Tumbulgum Public School (3277)
AMU REGION:	North Coast
STATE ELECTORATE:	Tweed
LOCAL GOVERNMENT AREA:	Tweed



## Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
$\bigcirc$	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Withdrawal Space - 1hb - (12.5 SQM)	Student Space (5)	
B00A - R0002 - Home Base - (47.58 SQM) - Teaching Space: 1	Student Space (22)	
B00A - R0003 - Practical Activities - 1hb - (24.06 SQM)	Student Space (11)	
B00A - R0005 - Movement - (29.87 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Home Base - (42.66 SQM) - Teaching Space: 1	Student Space (19)	
B00A - R0009 - Withdrawal Space - 1hb - (40.41 SQM)	Student Space (18)	
B00A - R0010 - Canteen - (8.42 SQM)	Not Applicable	Circulation or storage space.
B00C - R0003 - Staff Kitchen - (10.36 SQM)	Office (2)	
B00C - R0004 - Special Programs Room - (29.17 SQM)	Student Space (13)	
B00C - R0005 - Interview - (14.07 SQM)	Office (3)	
B00C - R9002 - Movement - (35.67 SQM)	Not Applicable	Circulation or storage space.
B00E - R0005 - Reading Area - (91.18 SQM)	Student Space (42)	