










VENTILATION AUDIT REPORT

SCHOOL:	Ulladulla Tutorial Centre (802)
AMU REGION:	Southern NSW
STATE ELECTORATE:	
LOCAL GOVERNMENT AREA:	

Siteplan

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Movement - (14.86 SQM)	Not Applicable	Circulation or storage space.
B00A - R0003 - Seminar Space - (27.77 SQM)	 Office (6)	
B00A - R0006 - Seminar/Technology Space - (34.79 SQM)	 Office (8)	
B00A - R1001 - Movement - (13.51 SQM)	Not Applicable	Circulation or storage space.
B00A - R1002 - Staff Study - (19.67 SQM)	 Office (4)	
B00A - R1005 - Interview - (8.87 SQM)	 Office (2)	
B00A - R1006 - Interview - (12.12 SQM)	 Office (3)	
B00A - R1007 - Staff Kitchen - (20.32 SQM)	 Office (5)	
B00A - R1008 - Clerical Office - (8.68 SQM)	 Office (2)	
B00A - R1009 - Computer Learning Space - (25.27 SQM)	 Student Space (11)	
B00A - R1010 - Independent Learning Space - (28.82 SQM)	 Student Space (13)	
B00A - R1012 - T.A.S. Outdoor Area - (44.12 SQM)	Not Applicable	Circulation or storage space.