


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Ulong Public School (3304)</b>
<b>AMU REGION:</b>	<b>North Coast</b>
<b>STATE ELECTORATE:</b>	<b>Coffs Harbour</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Coffs Harbour</b>

3304 - Ulong Public School  
Site Plan (11841)



1:480

Printed: 27-Mar-2021

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (20.85 SQM)	Not Applicable	Circulation or storage space.
B00A - R0003 - Home Base - (43.93 SQM) - Teaching Space: 1	● Student Space (20)	
B00B - R0002 - Movement - (8.31 SQM)	Not Applicable	Circulation or storage space.
B00B - R0004 - Home Base - (53.4 SQM) - Teaching Space: 1	● Student Space (24)	
B00B - R0005 - Withdrawal Space - 1hb - (10.93 SQM)	● Student Space (5)	
B00C - R0002 - Movement - (8.29 SQM)	Not Applicable	Circulation or storage space.
B00C - R0004 - Movement - (8.28 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Movement - (8.82 SQM)	Not Applicable	Circulation or storage space.
B00D - R0002 - Canteen - (12.48 SQM)	Not Applicable	Circulation or storage space.
B00I - R0001 - Reading Area - (59.98 SQM)	● Student Space (27)	
OS 503 12961 - OS 503 12961 - Admin Lib Staff/Principal/Clerk/Store - (152 SQM)	● Office (38)	