


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Upper Coopers Creek Public School (3760)</b>
<b>AMU REGION:</b>	<b>North Coast</b>
<b>STATE ELECTORATE:</b>	<b>Ballina</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Byron</b>

3760 - Upper Coopers Creek Public School  
Site Plan (10308)









1:535

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office - (11.54 SQM)	 Office (2)	
B00A - R0002 - Principal - (6.18 SQM)	 Office (1)	
B00A - R0003 - Reading Area - (36.45 SQM)	 Student Space (16)	
B00A - R0005 - Staff Room - (17.34 SQM)	 Office (4)	
B00A - R0006 - Movement - (5.05 SQM)	Not Applicable	Circulation or storage space.
B00B - R0006 - Practical Activities - 1hb - (12.84 SQM)	 Student Space (5)	
B00B - R0008 - Movement - (29.66 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	 Student Space (27)	