
VENTILATION AUDIT REPORT



SCHOOL:	Vacy Public School (3321)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Upper Hunter
LOCAL GOVERNMENT AREA:	Dungog

3321 - Vacy Public School Site Plan (12888)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces. The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Staff Kitchen - (10.42 SQM)	Office (2)	
B00A - R0004 - Staff Room - (29.26 SQM)	Office (7)	
B00A - R0005 - Principal - (14.47 SQM)	Office (3)	
B00A - R0007 - Duplicating Workroom - (10.62 SQM)	Office (2)	
B00A - R0011 - Clerical Office - (10.53 SQM)	Office (2)	
B00A - R0012 - Entry Vestibule - (10.65 SQM)	Not Applicable	Circulation or storage space.
B00C - R0006 - Home Base - (66.98 SQM) - Teaching Space: 1	Student Space (31)	
B00C - R0007 - Reading Area - (48.61 SQM)	Student Space (22)	
B00D - R0002 - Withdrawal Space - 1hb - (7.79 SQM)	Student Space (3)	
B00D - R0004 - Home Base - (60.58 SQM) - Teaching Space: 1	Student Space (28)	
B00I - R0002 - Canteen - (41.32 SQM)	Not Applicable	Circulation or storage space.
B00J - R0003 - Home Base - (64.55 SQM) - Teaching Space: 1	Student Space (29)	
B00J - R0004 - Reading Area - (64.24 SQM)	Student Space (29)	
OS 602 15143 - OS 602 15143 - Learning Unit - Standard With P.A.A (76 SQM)	Student Space (35)	
OS 603 12587 - OS 603 12587 - Learning Unit - Standard With P.A.A. A/C - (76 SQM)	Student Space (35)	