

VENTILATION AUDIT REPORT

SCHOOL:	Vineyard Public School (3329)
AMU REGION:	Western Sydney
STATE ELECTORATE:	Riverstone
LOCAL GOVERNMENT AREA:	Blacktown

3329 - Vineyard Public School
Site Plan (12891)










1:901

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (53.44 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0003 - Canteen - (11.1 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Home Base - (53.44 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0005 - Home Base - (53.44 SQM) - Teaching Space: 1	 Student Space (24)	
B00E - R0004 - Movement - (5.13 SQM)	Not Applicable	Circulation or storage space.
B00E - R0005 - Special Programs Room - (23.43 SQM)	 Student Space (10)	
B00E - R0006 - Practical Activities - 1hb - (10.46 SQM)	 Student Space (4)	
B00G - R0002 - Reading Area - (91.47 SQM)	 Student Space (42)	
OS 503 14514 - OS 503 14514 - Admin Lib Staff/Principal/Clerk/Store - (152 SQM)	 Office (38)	