VENTILATION AUDIT REPORT



SCHOOL:	Wakefield School (5582)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Lake Macquarie
LOCAL GOVERNMENT AREA:	Lake Macquarie



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
\bigcirc	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Canteen - (20.73 SQM)	Not Applicable	Circulation or storage space.
B00A - R0005 - Home Base - (53.62 SQM) - Teaching Space: 1	Student Space (24)	
B00A - R0006 - Home Base - (53.74 SQM) - Teaching Space: 1	Student Space (24)	
B00A - R0007 - Movement - (81.13 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Staff Room - (39.27 SQM)	Office (9)	
B00B - R0005 - Interview - (10.08 SQM)	Office (2)	
B00B - R0006 - Principal - (10.08 SQM)	Office (2)	
B00B - R0009 - Clerical Office - (12.77 SQM)	Office (3)	
B00B - R0010 - Home Base - (39.21 SQM) - Teaching Space: 1	Student Space (18)	
B00B - R0012 - Interview - (10.97 SQM)	Office (2)	
B00B - R0013 - Interview - (11.04 SQM)	Office (2)	
B00B - R0018 - Movement - (29.18 SQM)	Not Applicable	Circulation or storage space.
B00G - R0002 - Reading Area - (60.05 SQM)	Student Space (27)	
OS 601 10891 - OS 601 10891 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	
OS 601 12479 - OS 601 12479 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	
OS 601 19729 - OS 601 19729 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	