


VENTILATION AUDIT REPORT









SCHOOL:	Wakool Burraboi Public School (3336)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Murray
LOCAL GOVERNMENT AREA:	Murray River

3336 - Wakool Burraboi Public School
Site Plan (12893)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office - (23.04 SQM)	 Office (5)	
B00A - R0002 - Home Base - (53.64 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0003 - Home Base - (53.79 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0005 - Staff Room Annexe - (11.09 SQM)	 Office (2)	
B00B - R0001 - Home Base - (86.14 SQM) - Teaching Space: 1	 Student Space (39)	
B00B - R0007 - Staff Room - (16.74 SQM)	 Office (4)	
B00C - R0001 - Reading Area - (38.3 SQM)	 Student Space (17)	
B00D - R0001 - Movement - (13.09 SQM)	Not Applicable	Circulation or storage space.
B00G - R0001 - Reading Area - (59.84 SQM)	 Student Space (27)	